

# INDUSTRIAL COATING DEFECTS PREVENTION CHECKLIST

- Verify all parts are degreased and cleaned before finishing
- Confirm pretreatment steps are documented and followed
- Check parts for moisture before powder coating to prevent pinholes
- Ensure spray gun settings are calibrated for each job
- Verify film thickness meets specifications before curing
- Inspect booth environment for dust or contamination
- Confirm oven temperature is stable and within required range
- Review color standards and batch samples for consistency
- Inspect finished parts for orange peel, fisheyes or gloss variation
- Ensure packaged parts meet cleanroom or handling requirements

For precision coating services in Austin visit [CMTFinishing.com](http://CMTFinishing.com)